Ten-Year Airport Capital Improvement Program (ACIP) 2014-2023



Grosse Ile Municipal Airport

Grosse Ile, MI

December 2013

Michigan State Block Grant Program

Submitted by:

Mike Duker, Airport Manager

Prepared by:

C&S Companies 38777 Six Mile Road, Suite 202 Livonia, MI 48152



38777 Six Mile Road Suite 202 Livonia, MI 48152

Phone: 734-953-2571 Fax: 734-953-2652 www.cscos.com



MICHIGAN STATE BLOCK GRANT PROGRAM

TEN-YEAR AIRPORT CAPITAL IMPROVEMENT PROGRAM (CIP) FY-2014* to FY-2023

*ACIP includes current development year (2013 already programmed - minor changes acceptable)

| COMPANIE | | *ACIP includ | les current develo | pment year (2013 alrea | ndy programmed - m | inor changes acceptable | e) | | | | |
|---------------------|--|------------------------------|--------------------|----------------------------|-------------------------|--------------------------|--------------------------|-----------|-----------|-------------|---|
| Airport Name: | GROSSE ILE MUNICIPAL AIRPORT | | | | | | | | | | Date Prepared: 12/4/2013 |
| Associated City: | GROSSE ILE, MI | | | | | | | | | | Prepared By: C&S ENGINEERS, INC. |
| Sponsor: | TOWNSHIP OF GROSSE ILE | | | | | | | | | | Sponsor email address & phone: mduker@grosseileairport.com 734-675-0155 |
| Airport Identifier: | ONZ | | | | | | | | | | FINAL ACIP due to MDOT AERO: no later than 12/6/2013 |
| Development Year | Project Description | Shown on ALP? (Yes or No) | ACIP Code** | NPIAS Priority Rating** | Federal Entitlements | Federal Apportionment | Federal Discretionary | State | Local | Total | Remarks/Item Justification - Provide as much detail as possible |
| 2014 | Exhibit A and ALP Update | NA | PL PL MA | 66 | \$38,000 | \$0 | \$0 | \$1,000 | \$1,000 | \$40,000 | Update needed for Exhibit A Property Map. Existing property map is outdated. Airport needs an accurate map of property areas and land uses. Land releases are still not approved by the FAA. The ALP property map will also need to be updated to match. |
| 2014 | Pavement Repairs | Yes | RE RW IM | 70 | \$0 | \$0 | \$0 | \$67,500 | \$7,500 | \$75,000 | The runway and taxiway pavements continue to deteriorate. The PCI ratings do not accurately reflect the pavement failures that are occuring. Pavement repairs will likely be required until reconstruction can take place. |
| 2014 | Easement Acquisition | Yes | ST LA SZ | 44 | \$67,500 | \$0 | \$0 | \$3,750 | \$3,750 | \$75,000 | Easement acquistion to allow for tree clearing and the removal of the displaced threshold on Runway 4 22. |
| 2015 | Runway 4-22 Reconstruction - Design | Yes | RE RW IM | 70 | \$315,000 | \$0 | \$0 | \$17,500 | \$17,500 | \$350,000 | Runway 4-22 is now starting to deteriorate in the same way as Runway 17-35. It is believed that the same underlying issues and material issues exist in Runway 4-22 as in 17-35. The PCI of 97 does not accurately reflect the pavement failures that are occuring. Assumed asphalt reconstruction for the construction estimate. |
| 2015 | Taxiway A East Reconstruction - Design | Yes | RE TW IM | 66 | \$86,400 | \$0 | \$0 | \$4,800 | \$4,800 | \$96,000 | Taxiway A pavement continues to deteriorate in the same way as Runway 17-35. The PCI of 73 does not accurately reflect the pavement failures that are occurring. |
| 2015 | Pavement Repairs | Yes | RE RW IM | 70 | \$0 | \$0 | \$0 | \$67,500 | \$7,500 | \$75,000 | The runway and taxiway pavements continue to deteriorate. The PCI ratings do not accurately reflect the pavement failures that are occuring. Pavement repairs will likely be required until reconstruction can take place. |
| 2016 | Runway 4-22 Reconstruction - Construction | Yes | RE RW IM | 70 | \$312,350 | \$0 | \$3,547,120 | \$214,415 | \$214,415 | \$4,288,300 | Runway 4-22 is now starting to deteriorate in the same way as Runway 17-35. It is believed that the same underlying issues and material issues exist in Runway 4-22 as in 17-35. The PCI of 97 does not accurately reflect the pavement failures that are occuring. Assumed asphalt reconstruction for the construction estimate. |
| 2016 | Taxiway A East Reconstruction - Construction | Yes | RE TW IM | 66 | \$0 | \$0 | \$1,071,261 | \$59,515 | \$59,515 | \$1,190,290 | Taxiway A pavement continues to deteriorate in the same way as Runway 17-35. The PCI of 73 does not accurately reflect the pavement failures that are occuring. |
| 2017 | Carryover | NA | NA | NA | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | Carryover funding for future projects. |
| 2018 | General Aviation Apron Rehabilitation and Drainage - Design | Yes | RE AP IM | 60 | \$45,000 | \$0 | \$0 | \$2,500 | \$2,500 | \$50,000 | Pavement failure due to poor drainage. PCI ranges from 68-76 as of 2011. |
| 2018 | Pavement Repairs | Yes | RE RW IM | 70 | \$0 | \$0 | \$0 | \$54,000 | \$6,000 | \$60,000 | The runway and taxiway pavements continue to deteriorate. The PCI ratings do not accurately reflect the pavement failures that are occurring. Pavement repairs will likely be required until reconstruction can take place. |
| 2018 | General Aviation Apron Rehabilitation and Drainage, and Hole Bay - Construction | Yes | RE AP IM | 60 | \$255,000 | \$510,000 | \$0 | \$42,500 | \$42,500 | \$850,000 | Pavement failure due to poor drainage. PCI ranges from 68-76 as of 2011. Holding bay needed to facilitate aircraft movement on Taxiway C. |
| 2019 | Runway 17-35 Reconstruction - Design | Yes | RE RW IM | 70 | \$150,000 | \$93,000 | \$0 | \$13,500 | \$13,500 | \$270,000 | Runway 17-35 pavement continues to deteriorate. The PCI of 78 does not accurately reflect the pavement failures that are occuring. Assumed 3,800' length and asphalt reconstruction for the construction estimate. The ALP currently does not reflect a length of 3,800'. |
| 2019 | Taxiway A West Reconstruction - Design | Yes | RE TW IM | 66 | \$0 | \$61,200 | \$0 | \$3,400 | \$3,400 | \$68,000 | Taxiway A pavement continues to deteriorate in the same way as Runway 17-35. The PCI of 73 does not accurately reflect the pavement failures that are occuring. |

| 2019 | Hangar Roof Repair | NA | ST BD MS | 32 | \$0 | \$0 | \$0 | \$0 | \$43,000 | \$43,000 | Existing hangar roofs are failing and in need of repair. This will be funded 100% locally. |
|------|---|-----|----------|----|-----------|-------------|-----|-----------|-----------|-------------|---|
| 2020 | Runway 17-35 Reconstruction - Construction | Yes | RE RW IM | 70 | \$0 | \$3,009,960 | \$0 | \$167,220 | \$167,220 | \$3,344,400 | Runway 17-35 pavement continues to deteriorate. The PCI of 78 does not accurately reflect the pavement failures that are occuring. Assumed 3,800' length and asphalt reconstruction for the construction estimate. The ALP currently does not reflect a length of 3,800'. |
| 2020 | Taxiway A West Reconstruction - Construction | Yes | RE TW IM | 66 | \$0 | \$757,458 | \$0 | \$42,081 | \$42,081 | \$841,620 | Taxiway A pavement continues to deteriorate in the same way as Runway 17-35. The PCI of 73 does not accurately reflect the pavement failures that are occurring. |
| 2021 | LED MIRL, Other Lighting Improvements, AWOS Replacement | Yes | RE RW LI | 70 | \$150,000 | \$109,200 | \$0 | \$14,400 | \$14,400 | \$288,000 | Upgrade to more energy efficient LED lighting to improve energy costs, increase up-time, and decrease maintanence. |
| 2022 | Extend Airport Fence and Repair Gates - Phase II | Yes | ST EQ SE | 41 | \$106,200 | \$0 | \$0 | \$5,900 | \$5,900 | \$118,000 | Fencing needed for wildlife and security. |
| 2023 | SRE - Used Plow Truck | NA | ST EQ SN | 47 | \$62,550 | \$0 | \$0 | \$3,475 | \$3,475 | \$69,500 | Existing equipment not adequate for snow removal. |
| 2023 | SRE Building Site Work | Yes | ST BD SN | 39 | \$70,200 | \$0 | \$0 | \$3,900 | \$3,900 | \$78,000 | Parking pad and access road for SRE Building. |

^{**} In accordance with FAA Order 5100.39A, Appendix 6 - Fields need to be completed

| Airport and Associated City | | Concept(s) Development Year |
|------------------------------------|---|--|
| Grosse Ile Municipal Airpor | t Grosse lle, MI | 2014 |
| Concept(s) Description | | |
| Exhibit A and ALP Update | | |
| | | |
| Concept(s) Narrative/Justification | n (see guidance on preparing your project's | iustification) |
| | | ry map is outdated. Airport needs |
| | | eases are still not approved by the |
| | • | match. Using 2011 funding at 95% |
| match. | , | 3 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| PCI Information for pavement reha | abilitation (Please provide PCI rating(s) and | d year surveyed for proposed project) |
| Section | Date of PCI Survey | PCI Rating |
| | | |
| Section | Date of PCI Survey | PCI Rating |
| Section | Date of PCI Survey | FOI Nating |
| | | |
| Section | Date of PCI Survey | PCI Rating |
| | | |
| | <u> </u> | <u> </u> |
| ALP Verification (Please provide d | ate of approved ALP and applicable sheet | number(s) where proposed project is located) |
| Verify Project is on ALP | Date of Original FAA Approve | ed ALP Sheet Number(s) |
| | | |
| | N/A | |
| Date(s) of Approved Update(s) | | |
| | | |
| Comments | | |
| | | |
| | | |
| | | |

| Airport and Associated City | | Concept(s) Development Year | | |
|------------------------------------|---|--|--|--|
| Grosse Ile Municipal Airpor | t Grosse lle, MI | 2014 | | |
| Concept(s) Description | | | | |
| Pavement Repairs | | | | |
| | | | | |
| Concept(s) Narrative/Justification | (see guidance on preparing your project's | justification) | | |
| The runway and taxiway pa | vements continue to deteriorate | . The PCI ratings do not accurately | | |
| reflect the pavement failure | s that are occurring. Pavement r | repairs will likely be required until | | |
| reconstruction can take pla | ce. | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| PCI Information for pavement reha | abilitation (Please provide PCI rating(s) and | d year surveyed for proposed project) | | |
| Section | Date of PCI Survey | PCI Rating | | |
| TWAGI-10 | 2011 | 73 | | |
| Section | Date of PCI Survey | PCI Rating | | |
| RW422GI-10 | 2011 | 97 | | |
| Section | Date of PCI Survey | PCI Rating | | |
| RW1735GI-10 and -20 | 2011 | 78 and 74 | | |
| 1777 17 3301-10 and -20 | 2011 | 70 and 74 | | |
| ALP Verification (Please provide d | ate of approved ALP and applicable sheet | number(s) where proposed project is located) | | |
| Verify Project is on ALP | Date of Original FAA Approv | ed ALP Sheet Number(s) | | |
| | 0.04.4007 | | | |
| | N/A 3-21-1997 | | | |
| Date(s) of Approved Update(s) | | | | |
| | | | | |
| Comments | | | | |
| | | | | |
| | | | | |
| | | | | |

| Airport and Associated City | | Concept(s) Development Year | | | |
|-------------------------------------|---|--|--|--|--|
| Grosse Ile Municipal Airport | t Grosse lle, MI | 2014 | | | |
| Concept(s) Description | | | | | |
| Easement Acquisition | | | | | |
| | | | | | |
| Concept(s) Narrative/Justification | (see guidance on preparing your project's | justification) | | | |
| Easement acquisition to allo | ow for tree clearing and the remo | oval of the displaced threshold on | | | |
| Runway 4-22. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | abilitation (Please provide PCI rating(s) and | | | | |
| Section | Date of PCI Survey | PCI Rating | | | |
| | | | | | |
| Section | Date of PCI Survey | PCI Rating | | | |
| | | | | | |
| Section | Date of PCI Survey | PCI Rating | | | |
| | , | | | | |
| | | | | | |
| ALP Verification (Please provide da | ate of approved ALP and applicable sheet | number(s) where proposed project is located) | | | |
| Verify Project is on ALP | Date of Original FAA Approve | ed ALP Sheet Number(s) | | | |
| | 0.04.4007 | 0.1.001.11.11.1201(0) | | | |
| | N/A 3-21-1997 | | | | |
| Date(s) of Approved Update(s) | | | | | |
| | | | | | |
| Comments | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| Airport and Associated City | | | Concept | (s) Development Year | | |
|---|---------------|----------------------------------|--------------|------------------------------------|--|--|
| Grosse Ile Municipal Airport | Gross | e lle, MI | 2015 | | | |
| Concept(s) Description | | | | | | |
| Runway 4-22 Reconstruction - Design | | | | | | |
| | | | | | | |
| Concept(s) Narrative/Justification | (see quid | ance on preparing your project's | justificatio | n) | | |
| Concept(s) Narrative/Justification (see guidance on preparing your project's justification) Runway 4-22 is now starting to deteriorate in the same way as Runway 17-35. It is believed that the same underlying issues and material issues exist in Runway 4-22 as in Runway 17-35. The PCI of 97 does not accurately reflect the pavement failures that are occurring. Assumed asphalt reconstruction for the construction cost estimate. | | | | | | |
| PCI Information for pavement reha | ubilitation (| Please provide PCL rating(s) and | Lyear surv | reved for proposed project) | | |
| · | | | - | | | |
| Section | | PCI Survey | PCI Rating | | | |
| RW422GI-10 | 2011 | | 97 | | | |
| Section | Date of | PCI Survey | PCI Rati | I Rating | | |
| | | | | | | |
| Section | Date of | PCI Survey | PCI Rati | ng | | |
| ALP Verification (Please provide da | ate of app | roved ALP and applicable sheet r | number(s) | where proposed project is located) | | |
| Verify Project is on ALP | | Date of Original FAA Approve | ed Al P | Sheet Number(s) | | |
| | | 3-21-1997 | , a ruel | | | |
| | N/A | J-Z 1- 133 <i>1</i> | | 4 | | |
| Date(s) of Approved Update(s) | | | | | | |
| Comments | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |



GROSSE ILE MUNICIPAL AIRPORT GROSSE ILE, MI RUNWAY 4-22: FULL DEPTH RECONSTRUCTION WITH ASPHALT BASED ON FY 2013 DOLLARS E39.MKT.CRM

12/05/13

| | MDOT | DESCRIPTION | OLIANITITY. | | UNIT | TOTAL |
|-----|--------|--|-------------|----------|-----------------------------|------------------------------|
| NO | SPEC | DESCRIPTION | QUANTITY | UNITS | PRICE | TOTAL |
| 4 | 100041 | O SAFETY AND SECURITY | 4 | 1.0 | COE 000 00 | POE 000 00 |
| 2 | | D SAPETY AND SECURITY D MOBILIZATION AND GENERAL CONDITIONS | 1 | LS LS | \$25,000.00 \$135,000.00 | \$25,000.00 \$135,000.00 |
| 3 | | 5 PERMITS | 1 | LS | \$5,000.00 | \$5,000.00 |
| 4 | | 1 MISC. ELECTRICAL | 1 | LS | \$180,000.00 | \$180,000.00 |
| 5 | | UNCLASSIFIED EXCAVATION | 21,000 | Cyd | \$7.00 | \$147,000.00 |
| 6 | | O REMOVAL AND DISPOSAL OF BITUMINOUS PAVEMENT | 37,500 | Syd | \$4.00 | \$150,000.00 |
| 7 | | 2 REMOVAL AND DISPOSAL OF CONCRETE PAVEMENT | 89,300 | Syd | \$8.00 | \$714,400.00 |
| 8 | | 1 SUBBASE COURSE, TYPE 2 (SAND), COMPACTED MEASURE | 16,500 | Cyd | \$15.00 | \$247,500.00 |
| 9 | | 1 MISC. MDOT 6AA AGGREGATE DRAINAGE COURSE | 7,100 | Cyd | \$35.00 | \$248,500.00 |
| 10 | | O SOIL EROSION AND SEDIMENTATION CONTROL | 1 | LS | \$18,000.00 | \$18,000.00 |
| 11 | | O CRUSHED AGGREGATE BASE COURSE, MATERIAL AS SPECIFIED. | 5,100 | Cyd | \$35.00 | \$178,500.00 |
| • • | | COMPACTED IN PLACE | 0,.00 | ٥,۵ | φσσισσ | ψο,σσσ.σσ |
| 12 | 411062 | D BITUMINOUS AGGREGATE SURFACE COURSE, 20AAX COMPOSITION | 9,300 | Ton | \$90.00 | \$837,000.00 |
| 13 | | 5 BITUMINOUS TACK COAT, SPECIFIED EMULSIFIED ASPHALT | 7,000 | Gal | \$2.50 | \$17,500.00 |
| 14 | | O JOINT SEALING FILLER, TYPE III, HOT POURED | 2,000 | Lft | \$5.00 | \$10,000.00 |
| 15 | | 5 AIRPORT PAVEMENT MARKING, SOLID | 77,000 | Sft | \$0.50 | \$38,500.00 |
| 16 | | 9 AIRPORT PAVEMENT MARKING, 1/2 RATE, SOLID | 77,000 | Sft | \$0.50 | \$38,500.00 |
| 17 | | 1 MISC. DRAINAGE | 1 | LS | \$175,000.00 | \$175,000.00 |
| 18 | 705051 | 1 PIPE UNDERDRAIN 6", TYPE AS SPECIFIED | 11,200 | Lft | \$8.00 | \$89,600.00 |
| 19 | 705052 | 5 UNDERDRAIN CLEANOUT, AS SPECIFIED | 32 | Each | \$600.00 | \$19,200.00 |
| 20 | 800701 | MISC. STABILIZATION FABRIC | 648,000 | Sft | \$0.20 | \$129,600.00 |
| 21 | 901045 | O SEEDING WITH MIXTURE AND RATE, AS SPECIFIED | 12 | Acre | \$1,500.00 | \$18,000.00 |
| 22 | 905052 | O TOPSOILING FROM OFF-SITE, MATERIAL FURNISHED BY CONTRACTOR | 3,700 | Cyd | \$25.00 | \$92,500.00 |
| | | TOTAL CONOTRUCTION COOT | | | | *** ** * * * * * * * |
| | | TOTAL CONSTRUCTION COST | | | | \$3,514,300.00 |
| | | ENGINEERING & ADMINISTRATION (20%+/-) | | | | \$773,000.00 |
| | | CONTINGENCY (10%+/-) | | | | \$351,000.00 |
| | | TOTAL PROJECT COST | | | | \$4,638,300.00 |

ASSUMPTIONS:

Assume 14" concrete and 4" of asphalt to be removed. Assume replace 100' wide runway with 75' wide runway. Assume runway pavement section is same as proposed section for Runway 17-35 - 3" asphalt, 4" P-209, 20" P-154 per APTech report (assume P-154 is reduced to 14" and a 6" drainage layer is included per Somat geotechnical report). Assume remove shoulder pavement and replace with turf. Assume shoulder pavement section is 3" asphalt and 4" P-209. Assume existing concrete and asphalt will be removed and brought off site. Assume existing bituminous and concrete pavement on east shoulder (50' width) will be removed. Assume length is 4,846.

| Airport and Associated City | | | Concept | t(s) Development Year | | |
|--|-------------------|--|-------------------------------|--|--|--|
| Grosse Ile Municipal Airpor | t Gross | e IIe, MI | 2015 | | | |
| Concept(s) Description | | | • | | | |
| Taxiway A East Reconstruction - Design | | | | | | |
| | | | | | | |
| Concept(s) Narrative/Justification | (see guid | ance on preparing your project's | justificatio | n) | | |
| Taxiway A pavement contine 73 does not accurately reflectant taxiway was constructed in was placed in 1997. No oth 1997. | ues to dect the p | deteriorate in the same wavement failures that are an asphalt overlay was pl | ay as F coccurr aced in | Runway 17-35. The PCI of ing. The original concrete 1984. A concrete overlay | | |
| PCI Information for pavement reha | abilitation (| Please provide PCI rating(s) and | d year surv | veyed for proposed project) | | |
| Section | Date of | PCI Survey | PCI Rati | ng | | |
| TWAGI-10 | 2011 | | 73 | | | |
| Section | Date of | PCI Survey | PCI Rati | ng | | |
| | | | | | | |
| Section | Date of | PCI Survey | PCI Rati | ng | | |
| | | | | | | |
| ALP Verification (Please provide d | ate of app | roved ALP and applicable sheet r | number(s) | where proposed project is located) | | |
| Verify Project is on ALP | | Date of Original FAA Approve | ed ALP | Sheet Number(s) | | |
| ■ YES □ NO □ | J N/A | 3-21-1997 | | 4, 6 | | |
| Date(s) of Approved Update(s) | | | | | | |
| Comments | | | | | | |
| | | | | | | |
| | | | | | | |



GROSSE ILE MUNICIPAL AIRPORT GROSSE ILE, MI TAXIWAY A EAST (TAXIWAY C TO RUNWAY 4-22) - ASPHALT RECONSTRUCTION BASED ON FY 2013 DOLLARS

12/06/13

E39.MKT.CRM

| ITEM | MDOT | | | | UNIT | |
|------|--------|--|----------|-------|--------------|----------------|
| NO | SPEC | DESCRIPTION | QUANTITY | UNITS | PRICE | TOTAL |
| | | | | | | |
| 1 | 100041 | O SAFETY AND SECURITY | 1 | LS | \$25,000.00 | \$25,000.00 |
| 2 | 100040 | MOBILIZATION AND GENERAL CONDITIONS | 1 | LS | \$40,000.00 | \$40,000.00 |
| 3 | 125700 | 1 MISC. ELECTRICAL | 1 | LS | \$204,000.00 | \$204,000.00 |
| 4 | 152701 | 1 MISC. REMOVE EXISTING PCC PAVEMENT, VARIABLE THICKNESS | 13,000 | Syd | \$8.00 | \$104,000.00 |
| 5 | 154051 | 1 SUBBASE COURSE, TYPE 2 (SAND), COMPACTED MEASURE | 5,100 | Cyd | \$15.00 | \$76,500.00 |
| 6 | 154702 | 1 MISC. MDOT 6AA AGGREGATE DRAINAGE COURSE | 2,200 | Cyd | \$35.00 | \$77,000.00 |
| 7 | 209052 | O CRUSHED AGGREGATE BASE COURSE, MATERIAL AS SPECIFIED, | 1,500 | Cyd | \$32.00 | \$48,000.00 |
| | | COMPACTED IN PLACE | | | | |
| 8 | 411062 | D BITUMINOUS AGGREGATE SURFACE COURSE, 20AAX COMPOSITION | 2,650 | Ton | \$90.00 | \$238,500.00 |
| 9 | 603051 | 5 BITUMINOUS TACK COAT, SPECIFIED EMULSIFIED ASPHALT | 1,980 | Gal | \$2.50 | \$4,950.00 |
| 10 | 605053 | O JOINT SEALING FILLER, TYPE III, HOT POURED | 900 | Lft | \$5.00 | \$4,500.00 |
| 11 | 620051 | 5 AIRPORT PAVEMENT MARKING, SOLID | 5,000 | Sft | \$1.00 | \$5,000.00 |
| 12 | 701705 | 1 MISC. DRAINAGE | 1 | LS | \$30,000.00 | \$30,000.00 |
| 13 | 705051 | 1 PIPE UNDERDRAIN 6", TYPE AS SPECIFIED | 5,200 | Lft | \$8.00 | \$41,600.00 |
| 14 | 705052 | 5 UNDERDRAIN CLEANOUT, AS SPECIFIED | 12 | Each | \$600.00 | \$7,200.00 |
| 15 | 800701 | 0 MISC. STABILIZATION FABRIC | 117,000 | Sft | \$0.12 | \$14,040.00 |
| 16 | 901700 | 1 MISC. RESTORATION | 1 | LS | \$12,000.00 | \$12,000.00 |
| | | TOTAL CONSTRUCTION COST | | | | \$932,290.00 |
| | | CONTINGENCY (15%+/-) | | | | \$140,000.00 |
| | | ENGINEERING & ADMINISTRATION (20%+/-) | | | | \$214,000.00 |
| - | | TOTAL PROJECT COST | | | | \$1,286,290.00 |

ASSUMPTIONS:

Assume 17" concrete to be removed. Assume pavement section is same as proposed section for Runway 17-35 - 3" asphalt, 4" P-209, 20" P-154 per APTech report (assume P-154 is reduced to 14" and a 6" drainage layer is included per Somat geotechnical report).

| Airport and Associated City | | Concept(s) Development Year |
|------------------------------------|---|--|
| Grosse Ile Municipal Airpor | t Grosse lle, MI | 2015 |
| Concept(s) Description | | |
| Pavement Repairs | | |
| | | |
| Concept(s) Narrative/Justification | n (see guidance on preparing your project's | justification) |
| The runway and taxiway pa | avements continue to deteriorate | . The PCI ratings do not accurately |
| reflect the pavement failure | s that are occurring. Pavement r | repairs will likely be required until |
| reconstruction can take pla | ce. | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| PCI Information for pavement reha | abilitation (Please provide PCI rating(s) and | d year surveyed for proposed project) |
| Section | Date of PCI Survey | PCI Rating |
| TWAGI-10 | 2011 | 73 |
| Section | Date of PCI Survey | PCI Rating |
| RW422GI-10 | 2011 | 97 |
| Section | Date of PCI Survey | PCI Rating |
| | _ | |
| RW1735GI-10 and -20 | 2011 | 78 and 74 |
| ALP Verification (Please provide d | ate of approved ALP and applicable sheet | number(s) where proposed project is located) |
| Verify Project is on ALP | Date of Original FAA Approv | ed ALP Sheet Number(s) |
| | 0.04.4007 | |
| | N/A 3-21-1997 | |
| Date(s) of Approved Update(s) | | |
| | | |
| Comments | | |
| | | |
| | | |
| | | |

| Airport and Associated City | | | Concept | t(s) Development Year | |
|--|--------------|----------------------------------|--------------|------------------------------------|--|
| Grosse Ile Municipal Airpor | t Gross | e IIe, MI | 2016 | | |
| Concept(s) Description | | | • | | |
| Runway 4-22 Reconstruction | n - Con | struction | | | |
| | | | | | |
| Concept(s) Narrative/Justification | (see guid | ance on preparing your project's | justificatio | n) | |
| Runway 4-22 is now starting to deteriorate in the same way as Runway 17-35. It is believed that the same underlying issues and material issues exist in Runway 4-22 as in Runway 17-35. The PCI of 97 does not accurately reflect the pavement failures that are occurring. Assumed asphalt reconstruction for the construction cost estimate. | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| PCI Information for pavement reha | | | = | | |
| Section | Date of | PCI Survey | PCI Rati | ng | |
| RW422GI-10 | 2011 | | 97 | | |
| Section | Date of | PCI Survey | PCI Rati | ng | |
| | | | | | |
| Section | Date of | PCI Survey | PCI Rati | ng | |
| | | | | | |
| | | | | | |
| ALP Verification (Please provide d | ate of app | roved ALP and applicable sheet r | number(s) | where proposed project is located) | |
| Verify Project is on ALP | | Date of Original FAA Approve | ed ALP | Sheet Number(s) | |
| ■ YES □ NO □ | J N/A | 3-21-1997 | | 4 | |
| Date(s) of Approved Update(s) | | | | | |
| | | | | | |
| Comments | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |



GROSSE ILE MUNICIPAL AIRPORT GROSSE ILE, MI RUNWAY 4-22: FULL DEPTH RECONSTRUCTION WITH ASPHALT BASED ON FY 2013 DOLLARS E39.MKT.CRM

12/05/13

| | MDOT | DESCRIPTION | OLIANITITY. | | UNIT | TOTAL |
|-----|--------|--|-------------|----------|-----------------------------|------------------------------|
| NO | SPEC | DESCRIPTION | QUANTITY | UNITS | PRICE | TOTAL |
| 4 | 100041 | O SAFETY AND SECURITY | 4 | 1.0 | COE 000 00 | POE 000 00 |
| 2 | | D SAPETY AND SECURITY D MOBILIZATION AND GENERAL CONDITIONS | 1 | LS LS | \$25,000.00 \$135,000.00 | \$25,000.00 \$135,000.00 |
| 3 | | 5 PERMITS | 1 | LS | \$5,000.00 | \$5,000.00 |
| 4 | | 1 MISC. ELECTRICAL | 1 | LS | \$180,000.00 | \$180,000.00 |
| 5 | | UNCLASSIFIED EXCAVATION | 21,000 | Cyd | \$7.00 | \$147,000.00 |
| 6 | | O REMOVAL AND DISPOSAL OF BITUMINOUS PAVEMENT | 37,500 | Syd | \$4.00 | \$150,000.00 |
| 7 | | 2 REMOVAL AND DISPOSAL OF CONCRETE PAVEMENT | 89,300 | Syd | \$8.00 | \$714,400.00 |
| 8 | | 1 SUBBASE COURSE, TYPE 2 (SAND), COMPACTED MEASURE | 16,500 | Cyd | \$15.00 | \$247,500.00 |
| 9 | | 1 MISC. MDOT 6AA AGGREGATE DRAINAGE COURSE | 7,100 | Cyd | \$35.00 | \$248,500.00 |
| 10 | | O SOIL EROSION AND SEDIMENTATION CONTROL | 1 | LS | \$18,000.00 | \$18,000.00 |
| 11 | | O CRUSHED AGGREGATE BASE COURSE, MATERIAL AS SPECIFIED. | 5,100 | Cyd | \$35.00 | \$178,500.00 |
| • • | | COMPACTED IN PLACE | 0,.00 | ٥,۵ | φσσισσ | ψο,σσσ.σσ |
| 12 | 411062 | D BITUMINOUS AGGREGATE SURFACE COURSE, 20AAX COMPOSITION | 9,300 | Ton | \$90.00 | \$837,000.00 |
| 13 | | 5 BITUMINOUS TACK COAT, SPECIFIED EMULSIFIED ASPHALT | 7,000 | Gal | \$2.50 | \$17,500.00 |
| 14 | | O JOINT SEALING FILLER, TYPE III, HOT POURED | 2,000 | Lft | \$5.00 | \$10,000.00 |
| 15 | | 5 AIRPORT PAVEMENT MARKING, SOLID | 77,000 | Sft | \$0.50 | \$38,500.00 |
| 16 | | 9 AIRPORT PAVEMENT MARKING, 1/2 RATE, SOLID | 77,000 | Sft | \$0.50 | \$38,500.00 |
| 17 | | 1 MISC. DRAINAGE | 1 | LS | \$175,000.00 | \$175,000.00 |
| 18 | 705051 | 1 PIPE UNDERDRAIN 6", TYPE AS SPECIFIED | 11,200 | Lft | \$8.00 | \$89,600.00 |
| 19 | 705052 | 5 UNDERDRAIN CLEANOUT, AS SPECIFIED | 32 | Each | \$600.00 | \$19,200.00 |
| 20 | 800701 | MISC. STABILIZATION FABRIC | 648,000 | Sft | \$0.20 | \$129,600.00 |
| 21 | 901045 | O SEEDING WITH MIXTURE AND RATE, AS SPECIFIED | 12 | Acre | \$1,500.00 | \$18,000.00 |
| 22 | 905052 | O TOPSOILING FROM OFF-SITE, MATERIAL FURNISHED BY CONTRACTOR | 3,700 | Cyd | \$25.00 | \$92,500.00 |
| | | TOTAL CONOTRUCTION COOT | | | | *** ** * * * * * * * |
| | | TOTAL CONSTRUCTION COST | | | | \$3,514,300.00 |
| | | ENGINEERING & ADMINISTRATION (20%+/-) | | | | \$773,000.00 |
| | | CONTINGENCY (10%+/-) | | | | \$351,000.00 |
| | | TOTAL PROJECT COST | | | | \$4,638,300.00 |

ASSUMPTIONS:

Assume 14" concrete and 4" of asphalt to be removed. Assume replace 100' wide runway with 75' wide runway. Assume runway pavement section is same as proposed section for Runway 17-35 - 3" asphalt, 4" P-209, 20" P-154 per APTech report (assume P-154 is reduced to 14" and a 6" drainage layer is included per Somat geotechnical report). Assume remove shoulder pavement and replace with turf. Assume shoulder pavement section is 3" asphalt and 4" P-209. Assume existing concrete and asphalt will be removed and brought off site. Assume existing bituminous and concrete pavement on east shoulder (50' width) will be removed. Assume length is 4,846.

| Airport and Associated City | Concept(s) Development Year | | | | |
|--|-----------------------------------|--|-------------------------------|--|--|
| Grosse Ile Municipal Airport | 2016 | | | | |
| Concept(s) Description | | | | | |
| Taxiway A East Reconstruc | tion - C | onstruction | | | |
| | | | | | |
| Concept(s) Narrative/Justification | (see guid | ance on preparing your project's | justificatio | n) | |
| Taxiway A pavement contine 73 does not accurately reflectant taxiway was constructed in was placed in 1997. No oth 1997. | ues to o ect the p 1950. A | deteriorate in the same wavement failures that are an asphalt overlay was pl | ay as R coccurr aced in | Runway 17-35. The PCI of ing. The original concrete 1984. A concrete overlay | |
| PCI Information for pavement reha | bilitation (| Please provide PCI rating(s) and | d year surv | veyed for proposed project) | |
| Section | Date of | PCI Survey | PCI Rating | | |
| TWAGI-10 | 2011 | | 73 | | |
| Section | Date of | PCI Survey | PCI Rating | | |
| | | | | | |
| Section | Date of PCI Survey | | PCI Rating | | |
| Date of | | . C. Carroy | . To realing | | |
| | | | | | |
| ALP Verification (Please provide da | ate of app | roved ALP and applicable sheet r | number(s) | where proposed project is located) | |
| Verify Project is on ALP | Date of Original FAA Approved ALP | | Sheet Number(s) | | |
| ■ YES □ NO □ N/A | | 3-21-1997 | | 4, 6 | |
| Date(s) of Approved Update(s) | | | | | |
| | | | | | |
| Comments | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |



GROSSE ILE MUNICIPAL AIRPORT GROSSE ILE, MI TAXIWAY A EAST (TAXIWAY C TO RUNWAY 4-22) - ASPHALT RECONSTRUCTION BASED ON FY 2013 DOLLARS


12/06/13

E39.MKT.CRM

| ITEM | ITEM MDOT | | UNIT | | | |
|------|-----------|--|----------|-------|--------------|----------------|
| NO | SPEC | DESCRIPTION | QUANTITY | UNITS | PRICE | TOTAL |
| | | | | | | |
| 1 | 100041 | O SAFETY AND SECURITY | 1 | LS | \$25,000.00 | \$25,000.00 |
| 2 | 100040 | MOBILIZATION AND GENERAL CONDITIONS | 1 | LS | \$40,000.00 | \$40,000.00 |
| 3 | 125700 | 1 MISC. ELECTRICAL | 1 | LS | \$204,000.00 | \$204,000.00 |
| 4 | 152701 | 1 MISC. REMOVE EXISTING PCC PAVEMENT, VARIABLE THICKNESS | 13,000 | Syd | \$8.00 | \$104,000.00 |
| 5 | 154051 | 1 SUBBASE COURSE, TYPE 2 (SAND), COMPACTED MEASURE | 5,100 | Cyd | \$15.00 | \$76,500.00 |
| 6 | 154702 | 1 MISC. MDOT 6AA AGGREGATE DRAINAGE COURSE | 2,200 | Cyd | \$35.00 | \$77,000.00 |
| 7 | 209052 | O CRUSHED AGGREGATE BASE COURSE, MATERIAL AS SPECIFIED, | 1,500 | Cyd | \$32.00 | \$48,000.00 |
| | | COMPACTED IN PLACE | | | | |
| 8 | 411062 | D BITUMINOUS AGGREGATE SURFACE COURSE, 20AAX COMPOSITION | 2,650 | Ton | \$90.00 | \$238,500.00 |
| 9 | 603051 | 5 BITUMINOUS TACK COAT, SPECIFIED EMULSIFIED ASPHALT | 1,980 | Gal | \$2.50 | \$4,950.00 |
| 10 | 605053 | O JOINT SEALING FILLER, TYPE III, HOT POURED | 900 | Lft | \$5.00 | \$4,500.00 |
| 11 | 620051 | 5 AIRPORT PAVEMENT MARKING, SOLID | 5,000 | Sft | \$1.00 | \$5,000.00 |
| 12 | 701705 | 1 MISC. DRAINAGE | 1 | LS | \$30,000.00 | \$30,000.00 |
| 13 | 705051 | 1 PIPE UNDERDRAIN 6", TYPE AS SPECIFIED | 5,200 | Lft | \$8.00 | \$41,600.00 |
| 14 | 705052 | 5 UNDERDRAIN CLEANOUT, AS SPECIFIED | 12 | Each | \$600.00 | \$7,200.00 |
| 15 | 800701 | 0 MISC. STABILIZATION FABRIC | 117,000 | Sft | \$0.12 | \$14,040.00 |
| 16 | 901700 | 1 MISC. RESTORATION | 1 | LS | \$12,000.00 | \$12,000.00 |
| | | TOTAL CONSTRUCTION COST | | | | \$932,290.00 |
| | | CONTINGENCY (15%+/-) | | | | \$140,000.00 |
| | | ENGINEERING & ADMINISTRATION (20%+/-) | | | | \$214,000.00 |
| | | TOTAL PROJECT COST | | | | \$1,286,290.00 |

ASSUMPTIONS:

Assume 17" concrete to be removed. Assume pavement section is same as proposed section for Runway 17-35 - 3" asphalt, 4" P-209, 20" P-154 per APTech report (assume P-154 is reduced to 14" and a 6" drainage layer is included per Somat geotechnical report).



86-100 **71-85** 56-70 **41-55** 26-40 11-25 **0-10**

